

	<b>Hits</b>	<b>Search Text</b>	<b>DBs</b>	<b>Time Stamp</b>
<b>1</b>	<b>1</b>	"20050025565"	<b>US-PGPUB</b>	2005/02/22 14:39
<b>2</b>	<b>1</b>	"3570062".pn.	<b>USPAT</b>	2005/02/23 10:08
<b>3</b>	<b>65</b>	"411"/\$.ccls. and recess near tool	<b>USPAT</b>	2005/02/23 10:13
<b>4</b>	<b>0</b>	"411"/\$.ccls. and recess near tool near (thread threaded)	<b>USPAT</b>	2005/02/23 10:13
<b>5</b>	<b>7</b>	"4890947"	<b>USPAT</b>	2005/02/22 16:06
<b>6</b>	<b>1</b>	"4923322".pn.	<b>USPAT</b>	2005/02/23 10:00
<b>7</b>	<b>1</b>	"5173958".pn.	<b>USPAT</b>	2005/02/23 10:07
<b>8</b>	<b>0</b>	"spanner holes are threaded"	<b>USPAT; USOCR</b>	2005/02/22 16:30
<b>9</b>	<b>0</b>	"spanner holes being threaded"	<b>USPAT; USOCR</b>	2005/02/22 16:30
<b>10</b>	<b>1</b>	"spanner holes" adj (thread threaded)	<b>USPAT; USOCR</b>	2005/02/22 16:34
<b>11</b>	<b>205</b>	"spanner holes" and types	<b>USPAT; USOCR</b>	2005/02/22 16:38
<b>12</b>	<b>91</b>	"spanner holes" with (thread threaded)	<b>US-PGPUB; USPAT; USOCR</b>	2005/02/22 16:11
<b>13</b>	<b>88</b>	"spanner holes" with (thread threaded)	<b>USPAT; USOCR</b>	2005/02/22 16:30
<b>14</b>	<b>29</b>	"spanner holes" with threads	<b>USPAT; USOCR</b>	2005/02/22 17:12
<b>15</b>	<b>249</b>	"threaded holes" with screw with turning	<b>USPAT</b>	2005/02/22 17:53
<b>16</b>	<b>1</b>	"threaded spanner holes"	<b>USPAT; USOCR</b>	2005/02/22 16:32
<b>17</b>	<b>37</b>	"threaded washer" and "threaded holes"	<b>USPAT</b>	2005/02/22 18:05
<b>18</b>	<b>903</b>	"washer" with "threaded holes"	<b>USPAT</b>	2005/02/22 18:05
<b>19</b>	<b>181</b>	"washer" with "threaded holes" and (turn and turning)	<b>USPAT</b>	2005/02/22 18:05

	<b>Hits</b>	<b>Search Text</b>	<b>DBs</b>	<b>Time Stamp</b>
20	26	("0365037"   "0923633"   "0985491"   "1318455"   "1326626"   "1401302"   "2447299"   "2449284"   "2515303"   "3143366"   "3851983"   "3942466"   "4120082"   "4121532"   "4360349"   "4411549").PN.	US-PGPUB; USPAT; USOCR	2005/02/22 15:29
21	12	("0944461"   "1321081"   "2057990"   "2940784"   "3356324"   "3669393"   "4061298").PN.	US-PGPUB; USPAT; USOCR	2005/02/22 17:46
22	12	("1048261"   "2049104"   "3395601"   "4955744"   "4976071"   "5388877"   "5494368"   "5567100"   "5577872").PN.	US-PGPUB; USPAT; USOCR	2005/02/22 17:18
23	22	("2376089"   "3109663"   "3164354"   "3263549"   "3812895"   "4105058"   "4139315"   "4261666"   "4436445"   "4540304"   "4711760"   "4863326"   "4869694"   "5269622"   "5370472"   "5676511"   "5857798"   "5941669").PN.	US-PGPUB; USPAT; USOCR	2005/02/22 15:01
24	2	("2388633" "2397438").pn.	USPAT	2005/02/22 17:38
25	3	("2447299").URPN.	USPAT	2005/02/22 16:03
26	6	("2565606"   "2678840"   "3466074").PN.	US-PGPUB; USPAT; USOCR	2005/02/22 15:29
27	3	("2626427" "3453690"   "3471899").pn.	USPAT	2005/02/23 10:12
28	8	("2636533"   "2782827"   "2867258"   "4043239"   "4069102").PN.	US-PGPUB; USPAT; USOCR	2005/02/22 15:00
29	12	("3109663").URPN.	USPAT	2005/02/22 15:06

	<b>Hits</b>	<b>Search Text</b>	<b>DBs</b>	<b>Time Stamp</b>
30	26	("3143366"   "3604617"   "3699287"   "3708111"   "3770191"   "3961745"   "3990633"   "4010890"   "4101070"   "4120450"   "4205779"   "4214179"   "4226359"   "4322030"   "4344563"   "4360151"   "4435169"   "4449965"   "4457737"   "4484906"   "4507110"   "4553955"   "4693702"   "4753630"   "4753631").PN.	US-PGPUB; USPAT; USOCR	2005/02/22 16:11
31	9	("3173522"   "3909916"   "4192621"   "4304502"   "4367053"   "4496259"   "4607971"   "4610064").PN.	US-PGPUB; USPAT; USOCR	2005/02/22 15:11
32	6	("5511760").URPN.	USPAT	2005/02/22 17:47
33	2	("6446336" "6293184").pn.	USPAT	2005/02/22 13:22
34	24	(pins rods) with "assist turning"	USPAT	2005/02/22 18:02
35	192	403/16.ccls.	USPAT	2005/02/22 15:00
36	200	403/19.ccls.	USPAT	2005/02/22 15:25
37	114	403/21.ccls.	USPAT	2005/02/22 15:25
38	54	411/372.5.ccls.	USPAT	2005/02/22 14:44
39	86	411/372.6.ccls.	USPAT	2005/02/22 14:44
40	85	411/372.6.ccls. not 411/372.5.ccls.	USPAT	2005/02/22 14:51
41	109	411/374.ccls. not 411/372.6.ccls. not 411/372.5.ccls.	USPAT	2005/02/22 14:51
42	230	411/402.ccls. not 411/409.ccls.	USPAT	2005/02/22 17:32
43	79	411/409.ccls.	USPAT	2005/02/22 17:18

	<b>Hits</b>	<b>Search Text</b>	<b>DBs</b>	<b>Time Stamp</b>
<b>44</b>	<b>189</b>	<b>411/435.ccis.</b>	<b>USPAT</b>	<b>2005/02/22 17:35</b>
<b>45</b>	<b>0</b>	<b>fasteners near "for turning"</b>	<b>USPAT</b>	<b>2005/02/22 17:55</b>
<b>46</b>	<b>0</b>	<b>fasteners with "for turning"</b>	<b>USPAT</b>	<b>2005/02/22 17:55</b>
<b>47</b>	<b>8</b>	<b>pin with "assist turning"</b>	<b>USPAT</b>	<b>2005/02/22 17:56</b>
<b>48</b>	<b>0</b>	<b>pin with "for turning"</b>	<b>USPAT</b>	<b>2005/02/22 17:55</b>
<b>49</b>	<b>14318</b>	<b>pin with "turning"</b>	<b>USPAT</b>	<b>2005/02/22 17:55</b>
<b>50</b>	<b>1</b>	<b>threaded adj "spanner holes"</b>	<b>USPAT; USOCR</b>	<b>2005/02/22 16:34</b>
<b>51</b>	<b>1</b>	<b>threaded adj0 "spanner holes"</b>	<b>USPAT; USOCR</b>	<b>2005/02/22 16:34</b>